


Typical Flashing at Roof w/ Concrete Roof Tile



HCS 4.8



September 2009



UltraKote Products, Inc.
327 South 27th Avenue
Phoenix, Arizona 85009
Phone: 800.224.2344
Fax: 602.272.6445
www.ultrakoteproducts.com