


Typical Window Sill - Brick Mold



WM 5.3



September 2009



UltraKote Products, Inc.
 327 South 27th Avenue
 Phoenix, Arizona 85009
 Phone: 800.224.2344
 Fax: 602.272.6445
www.ultrakoteproducts.com